

STATE OF VERMONT  
PUBLIC SERVICE BOARD

Docket No. 7032

Joint Petition of Vermont Electric Power Company, Inc. ("VELCO"), Green Mountain Power Corporation ("GMP") and the Town of Stowe Electric Department ("Stowe") for a Certificate of Public Good pursuant to 30 V.S.A. § 248 authorizing VELCO to upgrade a substation in Moretown, Vermont; construct .3 miles of side by side, single pole tap; construct a switching station in Duxbury, Vermont; construct 9.4 miles of 115 kV transmission line; upgrade an existing GMP 34.5 kV subtransmission line; construct a substation in Stowe, Vermont; and for Stowe to construct 1.05 miles of 34.5 kV subtransmission line in Stowe, Vermont.

SURREBUTTAL TESTIMONY OF  
GEORGE E. SMITH  
ON BEHALF OF THE  
VERMONT DEPARTMENT OF PUBLIC SERVICE

June 27, 2005

Summary: The purpose of Mr. Smith's testimony is to respond to the prefiled rebuttal testimony of VELCO witness Ryan Johnson regarding the issues of appropriate transmission structure configurations, the resultant reliability of these configurations, and the impacts of these configurations on structure heights.

Surrebuttal Testimony  
of  
George E. Smith

**Identification of Witness and Qualifications**

Q. Please state your name.

A. My name is George E. Smith and I am a professional engineer licensed by the State of Vermont.

Q. Are you the same George E. Smith that prefiled testimony in this case on behalf of the Vermont Department of Public Service on April 11, 2005?

A. Yes, I am.

**Overview**

Q. What is the purpose of your testimony?

A. The purpose of my testimony is to respond to the prefiled rebuttal testimony of VELCO witness Ryan Johnson regarding the issues of appropriate transmission structure configurations, the resultant reliability of these configurations, and the impacts of these configurations on structure heights.

**Recommended Structure Type and Reliability Impact**

Q. In your prefiled direct testimony in this case, at pages 18 through 20, you discuss available techniques for lowering the height of the proposed transmission structures. Among the techniques you discuss is the use of braced post insulators. The prefiled rebuttal testimony of VELCO witness Ryan Johnson addresses the issue of shorter transmission structures within the context of so-called "hot line" maintenance. Given Mr. Johnson's testimony on this issue, has your thinking changed regarding the type of single pole, double circuit structure that would be appropriate for the proposed Lamoille project?

A. Yes. As a result of gaining a better understanding of VELCO's "hot line"

1 maintenance practices and techniques,<sup>1</sup> I now believe that the use of a single pole, double  
2 circuit braced post insulator configuration would not be appropriate for the proposed  
3 transmission project. Use of braced post insulators would not allow VELCO to perform  
4 "hot line" maintenance, i.e., perform certain maintenance functions on one circuit while  
5 keeping the other circuit in service.

6 Q. Is there a single pole, double circuit configuration that you believe would be appropriate  
7 for use in the proposed project, one that would allow for "hot line" maintenance?

8 A. Yes. A single pole, double circuit configuration using davit arms would permit  
9 VELCO to perform the necessary maintenance with either or both circuits energized. This  
10 structure type is presently used by VELCO on its Williston to Queen City line where a  
11 VELCO 115 kV line is co-located with a Green Mountain Power Corporation 34.5 kV  
12 line. (See VELCO's Response 11 to the Department's Eleventh Set of Information  
13 Requests which is attached to this testimony as Exhibit DPS-GES-11.) A drawing  
14 illustrating this type of structure is provided as Exhibit DPS-GES-12.<sup>2</sup>

15 Q. In the prefiled rebuttal testimony of VELCO witness Ryan Johnson at page 2, he  
16 discusses the reliability advantages of having the 115 kV and 34.5 kV lines on *separate*  
17 structures. Do you still believe that placing both the 115 kV and 34.5 kV circuits on a  
18 single pole, using davit arms, can provide appropriate reliability for the proposed  
19 Lamoille project?

20 A. Yes.

---

<sup>1</sup>See VELCO's Responses 2 through 11 to the Department's Eleventh Set of Information Requests which are attached to this testimony as Exhibit DPS-GES-2 through Exhibit DPS-GES-11.

<sup>2</sup>The drawing attached as Exhibit DPS-GES-12 is intended only as an illustration of a single pole, double circuit davit arm structure type. As discussed below, a single shield wire rather than the double shield wire shown on this drawing would provide adequate lightning protection. Also, the pole can be constructed of wood, rather than steel, and be directly embedded into the ground.

1 Q. Please explain.

2 A. First, I note that Department witness David Raphael recommends the use of single  
3 pole, double circuit structures for only 3.1 miles of the proposed 9.4 mile project. Hence,  
4 exposure to a double circuit failure is limited. Also, in the improbable event of a  
5 permanent double circuit failure, say due to a catastrophic structure failure or multiple  
6 line failure resulting from a large tree falling, this would result in a substantially less  
7 severe contingency than the worst contingencies that could impact the existing system.

8 Q. Please explain how the double circuit loss referenced above is less severe than the worst  
9 contingencies that could impact the existing configuration.

10 A. First, by comparing the one-line diagrams provided in the prefiled direct  
11 testimony of VELCO witness Kim Moulton,<sup>3</sup> the double circuit loss impact can be  
12 compared to a contingency case simulated by Ms. Moulton for the existing system,  
13 namely the opening of the 3313 breaker at Little River. The contingency results (refer to  
14 Exhibit KSM-2, page 10, Table 4) indicate that post contingency low voltages occur for  
15 2001 load levels and that non-convergence<sup>4</sup> occurs for 2002 load levels of approximately  
16 72 MW. For this contingency, (refer to Exhibit KSM-2, Appendix 7, Existing 2003) the  
17 Mountain line plus Dewey Hill substation loads totaling approximately 15 MW will  
18 remain tied to the remainder of the loop fed from the north via Morrisville. Note  
19 however, as can be observed from Exhibit KSM-2, page 6, Table 1 and Exhibit KSM-2,  
20 page 10, Table 4, this contingency is much less severe than one of the major  
21 contingencies, such as the opening of the 3312 breaker at Middlesex. This 3312  
22 contingency is much more severe than the 3313 open breaker contingency due to the fact  
23 that in addition to the Mountain Line plus Dewey Hill loads, the Waterbury loads are also

---

<sup>3</sup>See Exhibit KSM-2, Appendix 1, the one-line diagram labeled KSM-021; and Exhibit KSM-2, Appendix 6, the one-line diagram labeled KSM-023.

<sup>4</sup>Non-convergence, as experienced by a load flow simulation of a relatively weak transmission network such as that serving the Lamoille area, is an indication that voltage collapse is likely to occur in the event of a contingency. This collapse can cause outages over a sizeable portion of the local area.

1 tied to the single feed from the north. For this severe case, non-convergence occurs at  
2 approximately 50 MW of load.

3 Now, consider the case of the improbable double circuit outage between Little  
4 River and the proposed Stowe substation (refer to Exhibit KSM-2, Appendix 6, the one-  
5 line diagram labeled KSM-023). Upon the contingency, the 3313 breaker at Little River  
6 plus all four breakers in the Stowe ring bus will open to clear the faults on the two  
7 circuits. This will cause the 15 MW Mountain line plus Dewey Hill substation load to be  
8 shed thereby unburdening the 34.5 kV loop feed from the north via Morrisville. The  
9 result is that it is unlikely that other loads in the local area will be lost. Depending on the  
10 load levels and other factors, including the nature and location of the outage, some or all  
11 of the lost load can be restored by post contingency switching procedures.

12 Q. In Mr. Johnson's prefiled rebuttal testimony at page 2, he states that having both circuits  
13 on the same structure will increase the possibility of losing both circuits due to a danger  
14 tree falling. Do you believe that the petitioners' proposal, in which two separate structures  
15 are placed in a 100 ft right-of-way, is immune to this type of double circuit failure?

16 A. No. The petitioner's configuration places the centerline of the 34.5 kV circuit  
17 25 ft from the edge of the right-of-way. Therefore, a large danger tree falling from this  
18 side could conceivably cause a catastrophic failure of both circuits. One might  
19 characterize the petitioner's configuration to be roughly half as prone to this mode of  
20 catastrophic failure as the single pole, double circuit configuration.

21 Q. In Mr. Johnson's prefiled rebuttal testimony at page 2, he states that if both circuits are on  
22 the same structure and there was a catastrophic failure of the structure, both circuits  
23 would be lost. Further, at page 3, Mr. Johnson recommends that if a single pole, double  
24 circuit configuration is to be used, that the poles should be constructed of steel rather than  
25 wood, and that the structures should have concrete foundations rather than be directly  
26 embedded into the ground. Do you share Mr. Johnson's concerns with possible  
27 catastrophic structural failures and the need for structures to be made of steel poles with

1 concrete foundations?

2 A. No. While minimizing the risk of structural failures and using steel poles with  
3 concrete foundations may be required for some bulk transmission applications, I don't  
4 believe that the incremental costs, estimated by VELCO to be an additional \$900,000 per  
5 mile, would be justified for the proposed project.

6 Q. What is the basis for your conclusion?

7 A. I base this on several factors including the impact of the event, the likelihood of  
8 the event occurring, and VELCO's experience with embedded wood pole structures. With  
9 regard to the impact of the event, should such an improbable double circuit outage occur,  
10 due to appropriate actions of the protective relay systems, the outage will be contained in  
11 the local area and therefore will not adversely impact the security of VELCO's bulk  
12 system and other connected customers. In addition, due to the location in the network as  
13 described above, load levels would have to be extremely high in order to cause even a  
14 local area outage. Second, I believe that the double circuit catastrophic failure mode event  
15 has a low probability of occurring due to the limited exposure (3.1 miles or less),  
16 VELCO's intention to perform adequate precautions with regard to danger trees that pose  
17 a potential threat to the line, and the relatively low likelihood of extremely severe weather  
18 events that could impose stresses beyond the design capability of the line. Third, I have  
19 reviewed VELCO's outage data base that was provided in Response 14 to the  
20 Department's Eleventh Set of Information Requests, attached as Exhibit DPS-GES-13,  
21 and observe that the only structure failures experienced over the last 20 years have been  
22 cross arm failures. There have been no failures of embedded poles on the VELCO system.  
23 This is based on the experience with some 400 miles of 115 kV transmission lines.  
24 Granted, this is based on VELCO's experience with H-frame structures which in some  
25 ways are more robust than single pole structures, but it does point to the fact that  
26 properly installed and maintained embedded poles, given their past history of exposure to  
27 extreme weather events, including the ice storm of 1998, can provide reliable  
28 performance. I also note that VELCO is in the process of using embedded wood

1 structures for its construction of the Irasburg to Mosher's tap single pole, double circuit  
2 line.

3 Q. Does VELCO provide a quantitative analysis of the expected reliability of steel poles  
4 with concrete foundations versus the reliability of directly embedded wood poles to  
5 support its recommendations?

6 A. No. In Petitioners' Response 21 to the Department's Eleventh Set of Information  
7 Requests, attached to this testimony as Exhibit DPS-GES-14, VELCO provides only  
8 qualitative justification for the incremental expenditure of \$900,000 per mile for steel  
9 structures with concrete foundations. Given the impact of a double circuit outage, the  
10 likelihood of the event occurring, and VELCO's experience with embedded wood pole  
11 structures, I believe that this level of incremental expenditure cannot be justified. Also,  
12 this mode of construction may require use of larger construction equipment creating the  
13 potential for adverse environmental impact to the ROW during construction.

14 **Impact on Structure Height**

15 Q. Will the single pole, double circuit structures with davit arms that you recommend be  
16 taller than the 115 kV single pole, single circuit davit structures proposed by the  
17 petitioners?

18 A. Yes.

19 Q. How much taller do you estimate them to be?

20 A. The use of double circuits on a single pole requires that three of the phase  
21 conductors, instead of two, be placed on one side of the structure. Using the spacing  
22 scaled from the structures used for the Queen City line (refer to Exhibit DPS-GES-12),  
23 this would add approximately 13 ft to the height of the structures. (Note that VELCO uses  
24 a vertical spacing of 15 ft, rather than 13 ft, for their proposed single pole, single circuit  
25 115 kV structures.)



1 Q. Can the heights of the single pole, double circuit davit structures be mitigated by the same  
2 measures that you suggested in your prefiled direct testimony on pages 18 through 20?

3 A. With the exception of the use of braced post insulators, yes. Reducing the height  
4 of the shield wire above the topmost conductor provides a 4.5 ft reduction. Reducing the  
5 vertical spacing between two of the conductors from 15 ft to 13 ft affords an additional  
6 2 ft. (The increase assumed above by adding the third conductor already assumes a  
7 spacing of 13 ft between conductors, so only one 2 ft savings can be achieved.) Therefore,  
8 the net pole height increase above that of the petitioners' proposed 115 kV structure by  
9 going to a single pole, double circuit davit configuration is 6.5 ft. I also note that neither  
10 of these measures significantly affects the potential for vegetation contact as these  
11 measures do not impact the height of the bottom conductor.

12 Q. In his rebuttal testimony at page 4, Mr. Johnson comments on the shield angle  
13 calculations at pages 18 and 19 of your prefiled direct testimony. In VELCO's Responses  
14 27 and 36 to the Department's Eleventh Set of Information Requests, which are attached  
15 to this testimony as Exhibit DPS-GES-15 and Exhibit DPS-GES-16 respectively,  
16 Mr. Johnson further comments on this subject. Based on these comments, do you have  
17 anything to add to help clarify this issue?

18 A. Yes. First, it is apparent that Mr. Johnson and I used different definitions of angle  
19 in our statements and that this has been the source of some confusion. Accepting  
20 Mr. Johnson's definition of the angle as being measured from the vertical plane of the  
21 shield wire to the top conductor, with the shield wire at the apex, we agree that the shield  
22 angle of the configuration as proposed by VELCO is approximately 30 degrees. Reducing  
23 the height of the top portion of the pole (lowering the shield wire) by 4.5 ft, increases this  
24 angle to approximately 45 degrees.

25 Q. Doesn't increasing the shield angle to 45 degrees result in reduced lightning protection?

26 A. Not necessarily. It is important to note that reducing the pole height also reduces  
27 the surge impedance of the ground wire which in turn can enhance the lightning



1 protection. I note that in Response 38 to the Department's Eleventh Set of Information  
2 Requests, which is attached as Exhibit DPS-GES-17, VELCO has not performed any  
3 analysis to substantiate its reliability concerns with a shield angle greater than 30 degrees.  
4 Perhaps more importantly, and as I stated in my prefiled direct testimony (page 18,  
5 line 20 through page 19, line 6), most of VELCO's 115 kV structures in the field today  
6 employ shield angles of 45 degrees. And finally, I note that the majority of lightning  
7 incidents involving shield failures result in a momentary interruption to the circuit lasting  
8 only a second or two, and as such do not pose significant threats to reliability.

9 Q. In his rebuttal testimony at page 3, Mr. Johnson expresses VELCO's concerns with  
10 reducing pole height by reducing span length. In Response 24 to the Department's  
11 Eleventh Set of Information Requests, which is attached as Exhibit DPS-GES-18,  
12 Mr. Johnson acknowledges that reducing the span length does not lower the conductor at  
13 mid-span, and in Response 25 to the Department's Eleventh Set of Information Requests,  
14 which is attached as Exhibit DPS-GES-19, VELCO employee Mr. Wright states that any  
15 reduction in conductor height has a direct effect on vegetation height that can be tolerated  
16 *inside* of the right-of-way. How does this impact your recommendation of using reduced  
17 span length to achieve reduced pole heights?

18 A. I understand VELCO's concerns and believe that they should be given due  
19 consideration with regard to this aesthetic mitigation option. I note that the concerns do  
20 not apply at mid span, but increase very slightly at first, then to a higher degree as one  
21 approaches the structures. As I stated in my prefiled testimony, a substantial portion of  
22 the proposed construction already uses spans on the order of 300 ft, so application of this  
23 option would in fact be limited. Also, there may be other factors governing placement of  
24 the poles that may rule out this option in some areas. I recommend that the decision to use  
25 this option to achieve pole height reduction be made on a structure-by-structure basis in  
26 the context of the potential for aesthetic enhancement, the local terrain, surrounding  
27 vegetation, and other relevant factors.

28  
29 Q. Does this conclude your prefiled surrebuttal testimony.

30 A. Yes.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 2 of 39

Requests Relating to Prefiled Rebuttal Testimony of Ryan C. Johnson

2. Refer to Ryan Johnson's Rebuttal Testimony at p. 2, A3. In Mr. Johnson's response, does he assume that the workers are climbing the poles in order to perform "hot" line maintenance?

Yes.

Response provided by Jeff Wright.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 3 of 39

3. Refer to Ryan Johnson's Rebuttal Testimony at p. 2, A3. For those structure configurations that do not lend themselves to "hot" line maintenance using VELCO's pole climbing techniques, does VELCO presently have the means to employ "hot" line maintenance other than pole climbing? For example, do VELCO employees have the equipment and training to work from a bucket to perform line maintenance?

No.

Response provided by Jeff Wright.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 4 of 39

4. If VELCO does not presently have the means described above, please provide an estimate of the cost of acquiring the necessary equipment to perform "hot" line maintenance along the Lamoille 115 kV ROW. Please briefly describe the type of equipment that VELCO would propose and list the advantages and disadvantages of its use.

The prices range from \$500,000 to \$750,000 for the unit. A tractor and trailer to haul the unit would cost another \$150,000.

VELCO has researched the logistics of a track mounted bucket truck that we could use for energized line work on the VETCO 450 kV DC line and on vertical construction lines like the Derby to Richford and Mosher's Tap to Irasburg lines. We determined that fully utilizing a unit like this would add an unnecessary layer of complexity to performing the work. The transportation requirements would mean added resources and cost, the maintenance on a vehicle like this is very stringent, costly and in some cases the damage to the ground would be unacceptable to landowners, meaning expensive ground repairs. These were the primary reasons that we decided against changing our work methods and to continue climbing the poles.

Response provided by Jeff Wright.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 5 of 39

5. Do other means of hot line maintenance such as working from buckets involve the same clearance issues as pole climbing techniques? Please explain.

OSHA Standard 1910.269 addresses all live line work and the same minimum approach distances apply to line workers working from a bucket truck as those working from the pole.

Response provided by Jeff Wright.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 6 of 39

6. For VELCO's proposed davit arm structures, how does a reduction in vertical spacing of davits, while keeping davits the same length, reduce working clearances or otherwise complicate VELCO's "hot" line procedures?

The first step in performing an insulator or davit arm change out is to grasp the conductor with hot sticks and the necessary rigging. After the conductor is gripped adequately, the conductor is disconnected from the insulator allowing the conductor to be dropped to a safe distance away from the component that needs replacement. Reducing the vertical space results in reducing the distance that the conductor can be dropped.

Response provided by Jeff Wright.

7. Please provide the applicable clearance requirements, for "hot" line work, related to worker safety and identify the source (NESC, OSHA or other).

The applicable safety standards that state the necessary minimum approach distance requirements for live line maintenance is located in OSHA 1910.269 Table R6. Table R6 does not take into account the variables that a line worker encounters while performing live line maintenance such as worker size, workspace, ergonomic movement and the type of work to be performed.

Table R-6. - AC Live-Line Work Minimum Approach Distance

Nominal voltage in kilovolts phase to phase	Distance			
	Phase to ground exposure		Phase to phase exposure	
	(ft-in)	(m)	(ft-in)	(m)
0.05 to 1.0	(4)	(4)	(4)	(4)
1.1 to 15.0	2-1	0.64	2-2	0.66
15.1 to 36.0	2-4	0.72	2-7	0.77
36.1 to 46.0	2-7	0.77	2-10	0.85
46.1 to 72.5	3-0	0.90	3-6	1.05
72.6 to 121	3-2	0.95	4-3	1.29
138 to 145	3-7	1.09	4-11	1.50
161 to 169	4-0	1.22	5-8	1.71
230 to 242	5-3	1.59	7-6	2.27
345 to 362	8-6	2.59	12-6	3.80
500 to 550	11-3	3.42	18-1	5.50
765 to 800	14-11	4.53	26-0	7.91

Footnote(4) Avoid contact.

Response provided by Jeff Wright.



PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 8 of 39

8. For the proposed 115 kV line, please briefly describe all expected maintenance activities required (such as insulator replacement, hardware repair and adjustment) and provide the expected average frequency of each in terms of number of structures per year for the Lamoille 115 kV line.

The most common maintenance activity on any power line is the tightening of hardware and the repair of ground & static conductors and connections. These items are found mostly during a comprehensive aerial inspection, which is done on a ten year interval. It has been our experience that repairing the items found during these comprehensive inspections typically requires us to climb and work on approximately one-third of the structures, with increased problems found as the line ages.

In addition to these problems, we often find vandalized broken insulators, flashed insulators from lightning strikes, conductors that have been shot by vandals and other emergency problems. These are typically discovered during one of our routine patrols, which are done four times per year.

Response provided by Jeff Wright.

9. For a single pole, double circuit configuration using braced post insulators, such as VELCO is using for the line from Irasburg to Moshers tap, please briefly describe why both circuits need to be de-energized in order to perform routine maintenance on the 115 kV circuit. Would the equipment identified in response to Q4 above, if acquired, permit "hot" line work to be done with one or both circuits energized?

The minimum approach distances prevent line workers from safely climbing the pole while either circuit is energized. Utilization of an aerial lift could allow for some maintenance activities to be performed, which would be limited to working on the conductor attachment to the insulator. Each case would have to be evaluated prior to choosing the work method.

Response provided by Jeff Wright.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 10 of 39

10. For the Northern Loop project as proposed, for the portion from Irasburg to Moshers tap, or any other portion using construction similar to that from Irasburg to Moshers tap, does VELCO plan to remove portions of the 115 kV northern loop from service to perform maintenance on the 48kV circuit of VEC? Please explain.

VELCO plans to take the line out of service (both circuits) for all maintenance activities that require the line worker to climb the pole. In the case of the Irasburg to Mosher's Tap line, we can readily take the line out of service for maintenance because it is a loop feed. The proposed line to Stowe, however, is a radial feed that will be heavily relied upon and difficult to remove from service.


Response provided by Jeff Wright.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 11 of 39

11. Consider VELCO's 115 kV/ 34.5 kV single pole, double circuit configuration used for the circuit supplying VELCO's Queen City substation. Using VELCO's pole climbing techniques, could both circuits remain energized while performing maintenance on the 115 kV circuit? If not, would the 34.5 kV circuit need to be de-energized to perform "hot" line maintenance on the 115 kV circuit? Please explain.

VELCO is able to perform maintenance activities on either circuit with the other circuit energized.

Response provided by Jeff Wright.



LOOKING NORTH  
 VERGENNES SUBSTATION TO QUEEN CITY SUBSTATION  
 IN THE TOWN OF SOUTH BURLINGTON  
 MILE 25.44 TO MILE 26.07

Docket No. 7032  
 George E. Smith, Witness  
 Exhibit DPS-GES-12  
 Page 1 of 1

REV	DATE	DR	CK	DESCRIPTION
				<b>VELCO</b> VERMONT ELECTRIC POWER CO., INC. RUTLAND, VERMONT
				NEW HAVEN - QUEEN CITY 115kV LINE TYPICAL CROSS SECTION DOUBLE CIRCUIT STEEL
SCALE: NONE		DRAWN BY: DDL		APPROVED BY:
DATE: 01-14-03		CHECKED BY: MJM		DATE
DRAWING NUMBER:		CROSS SECTION 22		REV.
PLOT: 1:1				

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 14 of 39

14. Please describe each incident over the past twenty years of catastrophic structure failures experienced by VELCO.

See attached DPS11-VELCO-14 showing VELCO's Operation Department's list of all equipment- related outages on its system since 1986.

Response provided by Kim Moulton.

ir-perm-equip.xls

report	report_no	date	time	title	duration	fault_type	analy_by	analy_date
01-1987	1987-001	1/17/1987	15:16	Essex K25 breaker: Operated due to a failed 115KV L/A on the E. Avenue 115/13.8KV transformer.	6.11	-	-	-
01-1991	1991-001	1/8/1991	23:13	Middlebury 230-3 and VB72 C/S's: Operated due to defective 115KV fuses on the VB72 cap bank.	1.86	-	-	-
02-1987	1987-002	2/9/1987	07:26	New Haven H74 breaker: Operated due to equipment failure.	4.40	-	-	-
02-1988	1988-002	1/18/1988	15:40	E. Fairfax X19 breaker: Operated due to insulator failure at VEC's Cambridge #3 substation.	.000	-	-	-
02-1991	1991-002	1/13/1991	02:58	Middlebury H72, W. Rutland K30, Florence H84,B10,B11,B12 breakers: Operated due to a defective VB72 interrupt	.716	-	-	-
02-1994	1994-002	1/22/1994	11:59	Highgate H60, H10, H11 and Converter S.B1 breakers: Operated due to a broken insulator at Highgate sub.	.066	-	-	-
03-1987	1987-003	2/22/1987	14:41	Essex X62 and X66 breakers: Operated due to a failed insulator on the 34.5KV bus PT fuse holder.	4.15	-	-	-
03-1988	1988-003	1/19/1988	15:33	Hartford H83 breaker: Operated due to a failed but insulator in CVPS' 46KV system.	.000	-	-	-
04-1990	1990-004	3/10/1990	11:30	E. Fairfax X29 breaker: Operated due to a failed insulator in VEC's 46KV system.	.800	-	-	-
04-1991	1991-004	2/14/1991	17:42	Bennington Y25 Breaker: Operated when a sleeve pulled apart on NEPCO's portion of the Y25 line.	.400	-	-	-
04-1993	1993-004	2/7/1993	23:30	Vermont Yankee K186 breaker: Operated when a 46KV-69KV fault cause CVPS' 115/46KV transformer to fail.	.000	-	-	-
04-1994	1994-004	2/3/1994	15:24	Converter S.B1 and N.B1 breakers: Operated when HQ's power source to Bedford was interrupted.	.700	-	-	-
05-1987	1987-005	3/22/1987	20:01	Essex X62 and X66 breakers: Operated due to a failed PT at GMP's 34.5KV Essex substation.	18.8	-	-	-
05-1991	1991-005	2/16/1991	05:22	Bennington K4, K6, H37 and Y73 Breakers: Operated on Transformer Differential due to a Failed Insulator.	8.95	-	-	-
06-1986	1986-006	2/21/1986	18:42	Blissville H30 breaker: Operated due to a line fault in CVPS's 46KV system.	27.8	-	-	-
06-1987	1987-006	3/25/1987	17:05	Bennington Y73 breaker: Operated due to an insulator failure on the 259 disconnect.	6.81	-	-	-
06-1989	1989-006	3/24/1989	12:52	E. Fairfax X29 breaker: Operated due to failed insulator on VEC's #3 Cambridge tap.	.816	-	-	-
08-1986	1986-008	3/11/1986	03:20	E. Fairfax X29, Irasburg H39 and H15 breakers: Operated due to an insulator failure on the 34.5kV at VEC #3 ta	9.15	-	-	-
08-1987	1987-008	3/24/1987	01:23	Florence B10 breaker: Operated due to a phase down in VMCO's 46KV system.	6.46	-	-	-
08-1989	1989-008	3/29/1989	20:28	Irasburg H15 breaker: Operated due to transformer trouble in CU's system at Barton.	2.03	-	-	-
08-1991	1991-008	3/6/1991	13:00	Cold River H32 breaker: Operated when a line sleeve and two insulators failed on CVPS' 44KV line.	.850	-	-	-
09-1991	1991-009	3/13/1991	22:27	Vermont Yankee 81-1T,379,79-40 and 1T breakers: Operated due to a fault caused by broken 345KV insulators.	120.	-	-	-
10-1991	1991-010	3/19/1991	09:40	Highgate H12 breaker: Operated when an underground terminal in SVE's 7.5KV system.	.500	-	-	-
10-1993	1993-010	4/23/1993	05:58	Hartford H83 and Windsor H21 breakers: Operated when an insulator failed on CVPS's 46KV bus at Taftsville.	.000	-	-	-
13-1993	1993-013	4/28/1993	10:56	New Haven H74 breaker: Operated when an L/A failed resulting in a 34.5KV to 12KV fault in GMP's system.	.000	-	-	-
16-1989	1989-016	5/21/1989	14:19	Bennington K4, K6, H37, Y73 breakers: Operated when an L/A failed on the 46KV side of the 115/46KV trans.	3.83	-	-	-
16-1990	1990-016	5/27/1990	03:46	Queen City X69 and B43 breakers: Operated due to damage caused by a failed PT at GMP's Moran #23 substation.	.000	-	-	-
16-1992	1992-016	5/14/1992	11:00	Ascutney K149 breaker: Operated due to a broken crossarm between Ascutney Tap and Bellows Falls.	1.83	-	-	-
17-1991	1991-017	4/23/1991	15:47	Bennington Y25 breaker: Operated due to failed L/A's at GMP's Dover substation.	.616	-	-	-
18-1986	1986-018	5/20/1986	17:51	Converter N.B1 and S.B1 breakers: Operated due to stuck 50N relay contacts on HQ's Bedford 120-3 breaker.	3.40	-	-	-
18-1992	1992-018	5/30/1992	17:27	Middlebury K30 and H72, Florence H84,B10,B11,B12 breakers: Operated due to failed L/A on Middlebury transform	6.28	-	-	-
19-1986	1986-019	5/29/1986	18:39	Highgate H10 breaker: Operated due to a downed static wire on CU's 48KV line.	2.55	-	-	-
20-1988	1988-020	5/31/1988	09:47	Queen City X69 breaker: Opened by SCADA, resulting in GMP's Queen City breakers to open due to a shorted diod	.066	-	-	-
21-1991	1991-021	5/8/1991	12:37	Vermont Yankee K186 breaker: Operated when CVPS' 153 C/S at Vernon Rd. substation failed.	26.5	-	-	-
23-1988	1988-023	6/9/1988	08:00	Hartford H83 breaker: Operated due to a failed tertiary L/A on the 115/45KV transformer.	6.86	-	-	-
24-1988	1988-024	6/9/1988	12:49	IBM 1592 breaker: Operated due to an out of adjustment interlock contact on the 5911 airbreak.	.050	-	-	-
24-1992	1992-024	8/24/1992	11:46	Florence H84,B10,B11,B12 and Blissville H30 breakers: Operated due to blown line pot CVPS's B-7.	.866	-	-	-
28-1991	1991-028	6/15/1991	22:22	Vermont Yankee 31-1T, 379, 79-40, 381 and 1% breakers: Operated due to a fault on the 381 line.	24.0	-	-	-
31-1991	1991-031	8/3/1991	13:20	E. Fairfax X29 breaker: Operated due to failed insulators at the Village of Hyde Park's substation.	1.91	-	-	-
32-1990	1990-032	7/10/1990	09:54	Middlesex X65 breaker: Operated due to a failed CT at GMP's Middlesex substation.	4.45	-	-	-
33-1992	1992-033	9/30/1992	22:14	Essex K21,K22,K23,K24,K25,X62,X66, Georgia K21, E. Avenue B64 breakers: Operated due to Bus Differential.	1.96	-	-	-
35-1988	1988-035	6/25/1988	20:46	Irasburg H16 breaker: Operated due to a failed L/A in CU's 48KV system.	.150	-	-	-
37-1989	1989-037	7/14/1989	06:08	Converter N.B1 and S.B1 breakers: Operated on bus differential due to failure of phase C of S.B1.1 breaker.	1.51	-	-	-
38-1992	1992-038	12/5/1992	04:58	Hartford H83 and Windsor H21 breakers: Operated when a grounding transformer failed at CVPS' Taftsvill sub.	.983	-	-	-
40-1989	1989-040	7/27/1989	05:46	Ascutney K149 breaker: Operated due to NEPCO's failed 340 switch at Bellows Falls.	.150	-	-	-
41-1990	1990-041	8/7/1990	10:34	Coolidge KT1 and K31 breakers: Operated when the KT1-32 breaker failure relay operated incorrectly.	3.50	-	-	-
41-1991	1991-041	9/19/1991	22:47	Sand Bar K22, Essex K22 and X66 breakers: Operated when a splice failed on the 115KV line.	16.0	-	-	-
42-1991	1991-042	9/21/1991	11:58	Cold River H33 breaker: Operated when a line PT failed at CVPS' Cavendish substation.	.616	-	-	-
47-1993	1993-047	8/1/1993	00:28	Essex and Sand Bar K22 breakers: Operated when a T-connector failed on the 115KV line.	6.41	-	-	-
48-1988	1988-048	8/10/1988	14:43	Ascutney K174 breaker: Operated due to a broken crossarm on PSNH's M127 line.	.466	-	-	-
49-1995	1995-049	8/22/1995	07:47	Barre X04 breaker: Operated due to insulator failure in GMP's 34.5KV system.	.136	-	-	-
50-1991	1991-050	12/26/1991	13:54	E. Fairfax X19 breaker: Operated due to a failed insulator at VEC's #4 Underhill substation.	1.01	-	-	-
56-1988	1988-056	9/30/1988	07:42	IJ60 Line: Granite K51 and K53, Irasburgh H39, St. Johnsbury X14 and X22 breakers: Operated due to a fault at	.250	-	-	-
58-1989	1989-058	9/22/1989	04:06	Vermont Yankee 81-1T and 381 breakers: Operated during a large load swing due to a relay set too light.	2.08	-	-	-
60-1987	1987-060	10/17/1987	12:51	K21 Line (Essex and Georgia): Operated due to a trip relay malfunction.	.350	-	-	-
62-1986	1986-062	7/26/1986	16:20	Florence H84, B10, B11, B12 breakers: Operated due to a failed bushing CT in the 115/46KV transformer.	53.7	-	-	-
62-1989	1989-062	9/23/1989	02:03	Vermont Yankee 381 and 81-1T breakers: Operated during hurricane Hugo due to a 381 line primary relaying prob	1.53	-	-	-
62-1995	1995-062	11/16/1995	11:54	Bennington Y25 breaker: Operated due to a burnt off phase on the Searsburg 258 disconnect.	1.225	-	-	-
64-1995	1995-064	12/8/1995	11:13	Vermont Yankee 1T and 81-1T breakers: Operated when unit tripped due to unstable reactor feed water valve con	1.96	-	-	-
65-1995	1995-065	12/13/1995	11:26	Vermont Yankee 1T breaker: Operated due to air leak.	4.516	-	-	-
68-1987	1987-068	11/18/1987	01:27	Ascutney K174 breaker: Operated due to a damaged insulator in PSNH's system.	.083	-	-	-
70-1986	1986-070	8/5/1986	17:00	Windsor H78 and H21, Hartford H83 breakers: Operated due to failed breaker bushings at CVPS Windsor sub.	3.06	-	-	-
70-1987	1987-070	12/30/1987	15:56	Georgia K21 breaker: Operated due to loss of SF6 gas.	39.0	-	-	-
70-1990	1990-070	12/4/1990	12:34	Cold River H31 breaker: Operated due to a fault in CVPS' 46KV system.	26.3	-	-	-
71-1990	1990-071	12/10/1990	06:34	Highgate VB60 breaker: Due to failure of one phase to open, the 48KV bus was taken out of service.	102.	-	-	-
71-1994	1994-071	8/24/1994	17:03	Queen City B43 breaker: Operated due to underground cable and L/A failure in BED's 13.8KV system.	.050	-	-	-
72-1994	1994-072	9/5/1994	16:27	Ascutney K149 breaker: Operated when 149 line tripped due to broken pole in NEPCO's system.	.016	-	-	-
73-1990	1990-073	12/4/1990	04:28	E. Fairfax X29 breaker: Operated due to hot line tie wire failure in VEC's 34.5KV system.	7.51	-	-	-
74-1986	1986-074	8/8/1986	15:11	Windsor H78 and H21 breakers: Operated due to a defective CT at CVPS' Taftsville substation.	1.21	-	-	-
76-1993	1993-076	9/21/1993	14:51	Vermont Yankee 379 and 381 breakers: Operated when an undetermined caused a trans. fault press. relay to oper	.916	-	-	-
78-1993	1993-078	10/1/1993	06:48	Sand Bar and Georgia K19, E. Fairfax X19 breakers: Operated due to a failed micromho module at Sand Bar.	2.80	-	-	-
79-1986	1986-079	8/12/1986	19:01	W. Rutland and N. Rutland K37, Blissville H76 breakers: Operated due to a fault caused by a broken crossarm.	20.4	-	-	-



sys\_config

vt_load	weather	cause	sys_cond	fault_origin	origin	perm_fault	velc_orig	prot_perf	inc_class	to_mgproper	published	preliminary	
714.10	N	EQ	N		S	TRUE	TRUE	I	RI	FALSE	TRUE	FALSE	
728.00	N	EQ	N		S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
753.20	N	EQ	N		S	TRUE	TRUE	U	RI	TRUE	TRUE	FALSE	
768.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
551.00	N	EQ	N		S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
857.00	N	EQ	N		S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
602.00	N	EQ	N		S	TRUE	TRUE	U	RI	TRUE	TRUE	FALSE	
718.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
773.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
802.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
679.00	W	EQ	N		NL	TRUE	FALSE	I	RI	TRUE	TRUE	FALSE	
840.00	N	EQ	G		NL	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
609.70	N	EQ	N		S	TRUE	TRUE	U	RI	TRUE	TRUE	FALSE	
660.00	I	EQ	N		S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
.00	S	EQ	N		D	TRUE	FALSE	U	RI	TRUE	TRUE	FALSE	
607.30	N	EQ	N		S	TRUE	TRUE	U	RI	TRUE	TRUE	FALSE	
731.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
.00	N	EQ	HCU	CV_EFAX-JOHN_X29	LI_TR_LINE	D	TRUE	FALSE	U	RI	TRUE	TRUE	FALSE
467.10	N	EQ	N		D	TRUE	FALSE	U	RI	TRUE	TRUE	FALSE	
704.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
702.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
656.00	N	EQ	N		S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE	
764.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
521.00	S	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
701.00	N	EQ	T		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
552.00	N	EQ	TX		S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
359.20	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
526.00	W	EQ	N		NL	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
627.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
.00	S	EQ	N		NS	TRUE	FALSE	I	MI	TRUE	TRUE	FALSE	
580.00	N	EQ	N		T	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
.00	E	EQ	VCU		D	TRUE	FALSE	U	RI	TRUE	TRUE	FALSE	
674.00	N	EQ	N		S	TRUE	TRUE	I	RI	TRUE	TRUE	FALSE	
678.00	N	EQ	D		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
675.00	N	EQ	D		T	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
655.00	N	EQ	T		S	TRUE	TRUE	U	RI	TRUE	TRUE	FALSE	
784.00	N	EQ	T		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
532.00	R	EQ	N		O	TRUE	FALSE	I	RI	TRUE	TRUE	FALSE	
592.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
721.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
605.00	N	EQ	N		S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
520.00	E	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
443.00	N	EQ	N		S	TRUE	TRUE	U	RI	TRUE	TRUE	FALSE	
538.00	S	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
513.00	N	EQ	N		NS	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
623.00	R	EQ	N		S	TRUE	TRUE	I	MI	TRUE	TRUE	FALSE	
567.00	N	EQ	N		L	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
623.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
459.00	N	EQ	N		L	TRUE	TRUE	C	QI	TRUE	TRUE	FALSE	
759.00	H	EQ	N		NL	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
680.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
848.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
711.00	N	EQ	HTG		NL	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
416.00	R	EQ	TG		NL	TRUE	FALSE	I	MI	TRUE	TRUE	FALSE	
576.00	N	EQ	T		S	TRUE	TRUE	I	MI	TRUE	TRUE	FALSE	
.00	E	EQ	N		T	TRUE	TRUE	I	RI	TRUE	TRUE	FALSE	
421.00	H	EQ	N		S	TRUE	TRUE	I	MI	TRUE	TRUE	FALSE	
755.00	N	EQ	N		NL	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
864.00	N	EQ	N		NS	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
756.00	N	EQ	N		NS	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
429.00	N	EQ	N		NL	TRUE	FALSE	U	MI	TRUE	TRUE	FALSE	
.00	N	EQ	N		D	TRUE	FALSE	I	RI	TRUE	TRUE	FALSE	
891.00	N	EQ	N		S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE	
761.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
596.00	N	EQ	N		S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE	
697.00	N	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
579.00	W	EQ	N		NL	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
525.00	S	EQ	N		D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE	
.00	N	EQ	D		D	TRUE	FALSE	U	RI	TRUE	TRUE	FALSE	
715.00	N	EQ	TX		NS	TRUE	FALSE	I	MI	TRUE	TRUE	FALSE	
669.00	N	EQ	N		L	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
.00	N	EQ	N		L	TRUE	TRUE	U	RI	TRUE	TRUE	FALSE	

87-1993	1993-087	11/1/1993 13:27	Converter N.B1 and S.B1 breakers: Operated when a current transformer failed at HQ's Rouville substation.	9.51			-	-
	1996-005	1/22/1996 11:16	Highgate H60, H10, and H11 breakers: Operated due to a failed insulator on the 48KV bus.	1.569			-	-
	1996-010	3/26/1996 01:21	Irasburg H16 breaker: Operated due to failed fuse holder in CU's 48KV system.	13.317			-	-
	1996-024	6/1/1996 15:26	Ascutney H70 breaker and 700 C/S: Operated due to failed insulator.	4.311			-	-
	1996-029	6/12/1996	Converter S.B1 and N.B1 breakers: Operated during an electrical storm when the Bedford T1 transformer failed.				-	-
	1996-036	6/26/1996 07:09	Barre X06 breaker: Operated due to a fault in GMP's 34.5KV system.	4.263			-	-
	1996-052	8/15/1996 22:23	Converter S.B1 and N.B1 breakers: Operated due to failed South transformer.	140.45			-	-
	1996-058	10/14/1996 13:36	Chelsea H80 breaker: Operated due to an insulator failure in WEC's 46KV system.	4.046			-	-
	1996-061	11/18/1996 06:48	Essex, Georgia, Converter, Granite, Middlebury voltages: Low voltages due to fault in GMP's 334.5KV system.	4.117			-	-
	1996-066	12/9/1996 03:59	Barre X06 breaker: Operated due to pole damage.	.399			-	-
	1997-003	2/17/1997 19:02	N. Rutland-Cold River-Coolidge K32 line: Operated due to broken crossarm on structure 64.	3.129			-	-
	1997-020	5/5/1997 07:42	Ascutney C7 breaker and 7A MOD: Operated due to unbalance.	16.299			-	-
	1997-021	5/8/1997 05:53	Coolidge K31-35 and K35 breakers: Operated due to a failed capacitor in a GCX relay for the K35 line.	3.121			-	-
	1997-073	11/5/1997 15:22	K19 & K22 & PV20 Lines: Operated due to failed conduc	10.193	SLG	DPH	11/11/1997	
	1998-001	1/1/1998 23:53	Blissville H29 breaker: Operated due to blown transformer fuse at CVPS Dorset substation.		Other	DPH	1/2/1998	
	1998-023	2/24/1998 19:59	Converter N.B1 and S.B1 breakers: Operated on loss of HQ's 1425/1428 Line.				-	-
	1998-005	2/11/1998 20:14	Converter N.B1 and S.B1 breakers: Operated on loss of HQ's 1425/1428 lines.		L-L ph 1-3	DPH	1/19/1998	
	1998-034	5/11/1998 16:28	N. Rutland H71 breaker and 710 C/S: Operated on transformer differential due to a failed insulator.		2LG ph 1-3	JRF	6/15/1998	
	1998-037	5/19/1998 18:45	Queen City X69 breaker and 690 C/S: Operated on transformer differential due to GMP's 32Y5 problem.		3LG	DPH	5/22/1998	
	1998-072	7/1/1998 07:35	Barre X63 breaker: Operated on transformer differential due to a failed 34.5KV Bus insulator.		SLG ph 3	JRF	7/7/1998	
	1998-077	7/8/1998 15:13	Florence B10 breaker: Operated due to a failed L/A in VMCO's 46KV system.		SLG ph 2	JRF	7/14/1997	
	1998-093	8/21/1998 07:16	Converter N.B1 and S.B1 breakers: Opened by SCADA due to failure of a deluge pump to operate.				-	-
	1998-117	10/21/1998 02:58	Converter N.B1 and S.B1 breakers: Moisture in junction box shorted transformer fault pressure relay				-	-
	1998-118	10/23/1998 23:53	Converter N.B1 and S.B1 breakers: Operated due to a faulty micro-switch in the transformer oil pressure relay				-	-
	1998-124	12/21/1998 23:25	Georgia and Sand Bar K19, E. Fairfax X67 breakers and Georgia 800 C/S: Operated due to failed L/A at Georgia.		SLG ph 2	JRF	12/22/1998	
	1999-005	3/1/1999 13:52	Coolidge Transformer Differential		Other	JRF	3/16/1999	
	1999-023	6/30/1999 19:54	k24 line - Barre-Berlin: Broken Cross Arm		SLG ph 3	JRF	7/1/1999	
	1999-075	10/11/1999 17:06	New Haven H74: Operated Due to a Faulty GCX Relay Capacitor.		Other	JRF	10/18/1999	
	1999-076	10/11/1999 20:59	New Haven H74: Operated Due to a Faulty GCX Relay Capacitor #2.		Other	JRF	10/18/1999	
	1999-078	10/15/1999 21:51	Bennington H37: Failed 46 kV Lightning Arrestor.		SLG ph 1	JRF	10/18/1999	
	1999-084	11/10/1999 17:28	Coolidge Transformer Differential: Failed Transformer Tertiary Lightning Arrestor.		2LG ph 1-3	JRF	11/11/1999	
	2000-020	5/23/2000 00:58	K22 Line: "B" phase compression T connector failure at structure in substation.		SLG ph 2	DEB	7/24/2002	
	2001-062	9/1/2001 09:46	East Fairfax Transformer Differential: 115/34.5 KV Transformer Failed.		Other	DEB	9/13/2001	
	2002-017	5/13/2002 19:02	K32 Line (COOL-COLD-NRUT) Operated to lockout, blown L/A at COOL.		2LG ph 1-3	DEB	5/21/2002	
	2002-047	8/5/2002 11:45	New Haven & Middlebury K63 breakers both operated once automatically		SLG ph 1	DEB	8/6/2002	
	2002-075	12/11/2002 11:23	ITIC Violation: CVPS Mendon B-86 operated and locked out.		2LG ph 1-3	DEB	1/2/2003	
	2003-004	3/29/2003 21:44	Vermont Yankee 379, K1, 381, 79-40 and Scobie 379 line terminal breakers opened due to 379 stuck beaker.		Other	JRF	3/29/1903	
	2003-007	4/11/2003 10:06	Sand Bar K20: Plattsburg Phase Shifting Transformer Failure		3LG	JRF	6/3/1903	
	2003-009	5/25/2003 18:06	Highgate Converter N.B1: Temporary Block Due to H.Q's 1428 Line Operation.		3LG	JRF	12/29/2003	
	2003-012	6/11/2003 00:30	Barre X04: Operated to lockout due to a failed line pot within GMP's system.		2LG ph 2-3	JRF	6/25/1903	
	2003-018	7/17/2003 06:34	Ascutney H70, H19, H20, and 700: Opened automatically on transformer differential.				-	-
	2003-032	9/7/2003 06:38	Barre K24: Open and locked out.				-	-
	2003-037	10/4/2003 12:23	Essex X10, X11 and 100: Opened automatically on transformer differential.				-	-
	2003-051	12/9/2003 09:31	Chelsea H81: Opened and closed automatically due to bus fault at CVPS Bethel sub.				-	-
	2004-001	1/16/2004 02:14	Highgate Converter Tripped: HQ 1429 Line Tripped		3LG	JRF	1/19/1904	
	2004-005	2/27/2004 09:16	Essex X20 & X21: Breakers Operated when the Pilot Scheme was turned off at GMP.		Equip. Fail	RAB	3/15/1904	
	2004-010	3/12/2004 23:46	Highgate H10: Permanent fault in T1 Transformer at Rock Tenn Plant.		2LG ph 1-3	rcs	3/23/2004	
	2004-012	3/23/2004 14:15	Middlesex X65: Operated to lockout due to failed lighting arrestor at GMP sub.		Gnd Unkni	rcs	4/6/2004	
	2004-013	4/2/2004 16:47	Highgate C220 and C230: Operated to lockout due to broken crossarm.		Gnd Unkni	rcs	4/6/2004	
	2004-015	4/7/2004 13:08	Essex/Statcom: Bus #2 differential/K98 breaker failure.		SLG ph 2	rcs	4/19/2004	
	2004-024	5/15/2004 09:28	North Rutland H71: Operated due to Insulator failed on CVPS's B4 circuit.		SLG ph 1	rcs	5/20/2004	
	2004-047	6/18/2004 06:41	Vermont Yankee 1T and 81-1T breakers: Operated when unit tripped due to a main transformer fire.		L-L ph 2-3	rcs	6/29/2004	
	2004-049	6/22/2004 17:07	Florence B10 Breaker: Operated to lockout due to broken crossarm.		L-L ph 2-3	rcs	6/28/2004	
	2004-077	7/22/2004 13:11	Ascutney K174: Operated to lockout due to a broken crossarm.		SLG ph 2	rcs / jlc	7/29/2004	
	2004-079	8/2/2004 21:45	Florence B12 Breaker: Operated to lockout due to blown L/A on 727 disconnect.		SLG ph 2	JJC	8/3/2004	
	2004-111	10/18/2004 20:58	Highgate Converter Tripped: HQ 120-2 breaker Failure at St. Cesaire.		Equip. Fail	JJC	10/28/2004	
	2005-003	1/13/2004 23:20	Highgate H11 C210 and C220 all opened for 48 KV bus differential.		Equip. Fail	JJC	2/8/2005	
	2005-008	2/12/2005 11:06	ITIC Violation: Bellows Falls #3 Transformer Differential Operated Due to Bad B Phase Tap		SLG ph 3	JJC	2/17/2005	
	2005-009	2/16/2005 11:36	Cold River H31 breaker: Operated due to a fault in CVPS 46KV system.		Other	JJC/JRF	2/16/2005	
	2005-014	4/22/2005 15:30	Cold River H32 Breaker: Operated due to a failed line VT on the B-12 circuit at CVPS Lator Avenue		3LG	JJC	4/26/2005	
	2005-015	4/23/2005 02:56	Berlin X90 Breaker: Operated due to a failed fuse disconnect insulator at GMP Berlin		3LG	JJC	4/26/2005	
	2005-017	4/23/2005 19:49	Hartford H83: Operated due to internal fault on CVPS Thetford transformer.		L-L ph 1-2	JJC/JRF	-	-
	2005-018	4/23/2005 16:16	Vermont Yankee 379 and 79-40 breakers tripped due to a broken 345 KV crossarm at PSNH structure 481.		SLG ph 1	JJC	4/28/2005	
	2005-019	4/30/2005 06:13	St. Albans Transformer Differential: X61 Source POT Failed.		3LG	JJC/JRF	4/3/2005	
	2005-025	5/19/2005 05:03	Highgate Converter: Main Breakers Tripped, S.Z6.B breaker Failure.		Equip. Fail	JJC	6/6/2005	

	773.00	N	EQ	N		NS	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
	864.0		EQ				TRUE	TRUE		RI	TRUE	TRUE	FALSE	
	480.0		EQ				TRUE	FALSE		RI	TRUE	TRUE	FALSE	
	584.0		EQ				TRUE	TRUE		MI	TRUE	TRUE	FALSE	
	766.0		EQ				TRUE	FALSE		MI	TRUE	TRUE	FALSE	
	676.0		EQ				TRUE	FALSE		RI	TRUE	TRUE	FALSE	
	635.		EQ				TRUE	TRUE		RI	TRUE	TRUE	FALSE	
	704.0		EQ				TRUE	FALSE		RI	TRUE	TRUE	FALSE	
	686.0		EQ				TRUE	FALSE		RI	TRUE	TRUE	FALSE	
	573.0		EQ				TRUE	FALSE		MI	TRUE	TRUE	FALSE	
	850.0		EQ				TRUE	TRUE		QI	TRUE	TRUE	FALSE	
	700.0		EQ				TRUE	TRUE		MI	TRUE	TRUE	FALSE	
	650.0		EQ				TRUE	TRUE		MI	TRUE	TRUE	FALSE	
	706.0	I	EQ			L	TRUE	TRUE		QI	TRUE	TRUE	FALSE	
Normal, load 675MW, Converter 217MW, McNeil off line	675	N	EQ			D	TRUE	FALSE	C	QI	TRUE	TRUE	FALSE	
	800	MW	S			NL	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE	
Normal w/o Highgate Converter, load 502 MW, McNeil off line	845	N	EQ			NL	TRUE	FALSE	I	MI	TRUE	TRUE	FALSE	
McNeil 47 MW; Converter 129 MW; North Rutland B2 Open; Lator Avenue B6 Open	685	N	EQ			S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
Nominal, Converter 130MW, McNeil 45MW	655	N	EQ			T	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE	
Normal: Converter 200 MW; McNeil 31 MW	747	R	EQ			S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE	
Nominal System; Converter 203MW; McNeil 50MW	747	N	EQ			S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE	
	697	N	EQ			S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE	
	475	N	EQ			S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE	
	581	N	EQ			S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE	
Converter 210MW; McNeil 15MW; Nominal System Configuration	560	R	EQ	Normal	VE_GEOR-SAND_K19	LI_TR_LINE	S	TRUE	TRUE	C	QI	TRUE	TRUE	FALSE
Converter 206 MW; McNeil OOS; Nominal System	821	MW	N	EQ	VE_COOL		T	TRUE	TRUE	I	MI	TRUE	TRUE	FALSE
Nominal System; Load 754MW; McNeil 50MW; Converter 193 MW	754	N	EQ	normal	VE_BARR-BERL_K24	LI_TR_LINE	L	TRUE	TRUE	C	QI	TRUE	TRUE	FALSE
Contingency System; Vergennes 3322 Closed; McNeil OOS for Maintenance	720	N	EQ		VE_NHVN		S	TRUE	TRUE	I	RI	TRUE	TRUE	FALSE
New Haven 499 Open; New Haven 7PF Open	700	N	EQ		VE_NHVN		S	TRUE	TRUE	I	RI	TRUE	TRUE	FALSE
Nominal System; Y25 Closed; Converter MW; McNeil MW	634	N	EQ		VE_BENN		S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE
Coolidge KT1 & KT1-32 Open	826	R	EQ		VE_COOL		S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE
See Op's description; Sys Load: 530MW; McNeil: 50MW; Conv: 67MW	530	N	EQ				L	TRUE	TRUE	I	QI	TRUE	TRUE	FALSE
Sys Load: 703MW; McNeil: 37MW; Conv: 200MW	703	N	EQ				S	TRUE	TRUE	C	MI	TRUE	TRUE	FALSE
Sys Load: 763MW; McNeil: 51MW; Conv: 213MW	763	R	EQ				L	TRUE	TRUE	C	QI	TRUE	TRUE	FALSE
See Op's description; Sys Load: 963MW; McNeil: 50MW; Conv: 213MW	963	N	EQ	abnormal			L	TRUE	TRUE	I	QI	TRUE	TRUE	FALSE
See Op's description; Sys Load: 912MW	912	N	EQ				D	TRUE	FALSE	C	QI	TRUE	TRUE	FALSE
Nominal	600	N	EQ	Normal			S	TRUE	TRUE		MI	TRUE	TRUE	FALSE
Nominal System, 770 MW, McNeil 15MW, Converter 202MW	770	N	EQ	Normal			NT	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE
Plattsburgh PAR Bypassed, OMS in service, K186 Line OOS	618	R	EQ				NL	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE
Plattsburgh PAR Bypassed, OMS In Service, McNeil OOS, Load 527MW	527	N	EQ				D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE
	699	N	EQ				S	TRUE	TRUE	C	RI	TRUE	TRUE	FALSE
	533	N	EQ				S	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE
	720	R	EQ	Normal			S	TRUE	TRUE	C	QI	TRUE	TRUE	FALSE
	895	N	EQ				NS	TRUE	FALSE	C	QI	TRUE	TRUE	FALSE
Nominal System, Plattsburgh PAR OOS, OMS Bypassed	750	S	EQ				NS	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE
	871	N	EQ				D	TRUE	FALSE	I	MI	TRUE	TRUE	FALSE
Plattsburgh PAR bypassed, Sandbar OMS bypassed.	642	N	EQ				D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE
	809	N	EQ				D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE
Plattsburgh PAR bypassed and Sandbar OMS Bypassed	740	N	EQ				D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE
Plattsburgh PAR bypassed, Sandbar OMS bypassed, 340 line out of service	755	N	EQ				S	TRUE	TRUE	C	QI	TRUE	TRUE	FALSE
Plattsburgh PAR OOS, Sandbar OMS inserted, Williston K23 breaker OOS for insp'n	730	N	EQ				D	TRUE	FALSE	I	QI	TRUE	TRUE	FALSE
VY at 516 MW when the fault occurred	708	N	EQ				NT	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE
Vermont Yankee OOS	807	R	EQ				D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE
	961	N	EQ				NL	TRUE	FALSE	C	QI	TRUE	TRUE	FALSE
Normal	839	N	EQ				D	TRUE	FALSE	C	RI	TRUE	TRUE	FALSE
Normal	675	N	EQ				NS	TRUE	FALSE	C	MI	TRUE	TRUE	FALSE
Normal	625	W	EQ	Normal			D	TRUE	FALSE		QI	TRUE	FALSE	FALSE
Normal	814	N	EQ	Normal			NT	TRUE	FALSE	C	QI	TRUE	FALSE	FALSE
Cold River H31 breaker reclosing blocked for CVPS tree crew.	822	N	EQ	Normal			NL	TRUE	FALSE	A	QI	TRUE	FALSE	FALSE
Cold River H32 auto blocked, CV Lator B-3 & B-12 Open	685	N	EQ	Normal			D	TRUE	FALSE	C	QI	TRUE	FALSE	FALSE
Normal	477	R	EQ	Normal			D	TRUE	FALSE	C	QI	TRUE	FALSE	FALSE
Normal	705	R	EQ	Normal			D	TRUE	FALSE	C	QI	TRUE	FALSE	FALSE
Normal	646	N	EQ	Normal			NL	TRUE	FALSE	C	RI	TRUE	FALSE	FALSE
Normal	530	N	EQ				S	TRUE	TRUE	C	QI	TRUE	FALSE	FALSE
Converter Shutdown in progress	549	N	EQ	Normal			S	TRUE	TRUE	C	MI	TRUE	FALSE	FALSE

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 21 of 39

21. Refer to Ryan Johnson's Rebuttal Testimony at p. 3, Q&A5. Please provide the rationale, assumptions, and all supporting structural calculations supporting the recommendation to use steel poles supported by concrete foundations.

The use of steel poles on concrete foundations is recommended over the use of direct embedded poles because:

- A properly designed steel pole and concrete foundation are more predictable than a direct embedded pole because it uses materials that are completely engineered. A wood pole can be unpredictable because mother nature created it and the potential defects that may be inside the pole are not obvious. Wood poles are specified to meet certain minimums, but they can have defects that create weak spots. Varying soil conditions can also affect the stability of the pole when direct embedded. Placing a steel pole on a properly engineered foundation creates a more stable environment for the pole.
- Discussions with other utilities have shown that steel structures utilizing concrete foundations are preferred over direct embedding due to longevity and reliability especially for critical circuits. Getting the steel pole out of direct contact with the soil has shown to give the pole a longer life span.
- VELCO has, since the inception of this project, reduced the level of desired reliability it wants from this project from what was originally proposed. Originally VELCO desired an H-frame 115 kV structure in a right-of-way with the 34.5 kV line 50 feet from the 115 kV structure. However, due to the close proximity of homes within the corridor, VELCO designed the proposed configuration. If VELCO is asked to construct single pole, double circuit lines then it feels steel poles with concrete foundations should be used to minimize the exposure for loss of one of these poles and in turn to maximize the electrical reliability to the area.

Response provided by Ryan Johnson.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 27 of 39

27. One of the pole height reduction measures suggested by Department witness Smith involves reducing the pole height measured from the top conductor to the static wire which decreases the cone angle from nominally 60 degrees to 45 degrees. Does VELCO believe that this particular measure will impact vegetation management?

No, but this would reduce the shield angle to what is considered the bare minimum for transmission line design on a transmission line that is critical to the Lamoille County area reliability.

Response provided by Ryan Johnson.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 36 of 39

36. Refer to Ryan Johnson's Rebuttal Testimony at p. 4, Q&A10. Does VELCO agree that Department witness Smith's "shield angle" calculation of approximately 60 degrees, using his definition whereby the angle is measured from a horizontal plane containing the topmost conductor up to the shield wire at the structure, corresponds to VELCO witness Johnson's shield angle of 34 degrees (approximately 30 degrees) measured from a vertical plane containing the shield wire to the top conductor?

Yes, but using the horizontal plane to measure the shield angle conflicts with the industry standard method of using the vertical plane.

Response provided by Ryan Johnson.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 38 of 39

38. Please provide all analyses quantifying and supporting VELCO's concerns with the reduction in reliability that would result from employing Department witness Smith's proposed pole height reduction by lowering the shield wire. Include the probable increased incidence of both momentary faults and permanent faults (those resulting from lightning induced equipment failure).

VELCO has not performed such analysis.

Response provided by Ryan Johnson.



PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 24 of 39

24. Refer to Ryan Johnson's Rebuttal Testimony at pp. 3-4, Q&A7. Does VELCO believe that lowering the pole height by using shorter spans and thereby reducing the sag cause the conductor to be lower at mid span than for the proposed configuration?

No, but this does result in a higher cost line both initially and for future maintenance. The point that was being made in Q&A7 of the rebuttal testimony was that as conductors on poles with reduced pole heights/shorter spans get further from mid-span and closer to the poles, they are closer to the ground than conductors on optimized pole heights/spans. The fact that overall the conductors on reduced pole height/shorter spans are closer to the ground, vegetation management becomes more of a concern.

Response provided by Ryan Johnson.

PSB Docket No. 7032  
Petitioners Response to DPS11  
June 13, 2005  
Page 25 of 39

25. Please describe why lowering the height of the pole increases the concern with vegetation management.

Any reduction in conductor height will have a direct effect on the vegetation that can be tolerated inside the right-of-way.

Response provided by Jeff Wright.